GENERAL INFORMATION:

Client Name	:			
Supplier	:		Factory	:
Inspection Date	:		Location	: HUAIAN, CHINA
Inspector(s) Code	:			
Authorizer	:			
Inspection Type	:	Pre-Shipment Inspection		
Product Description	:	ELECTRIC KETTLE		
Purchase Order No.	:			
Item/SKU/Style No.	:	153185, 153186		
P.O. Quantity	:	8872 Pieces		
Shipment Quantity	:	8872 Pieces		

INSPECTION RESULT SUMMARY:

1)	**Quantity check**	:	**Pass**
2)	**Workmanship**	:	**Fail,** Exceed the AQL and Refer to remark: 1
3)	**Product Description, Style, & Color Conformity**	:	**Fail,** Refer to remark: 2, 3, 4
4)	**Labeling, Printing, Marking & Barcode**	:	**Pass**
5)	**Packaging & assortment**	:	**Pass**
6)	**Shipping marks**	:	**Pass**
7)	**On-site test and Data measurement**	:	**Pass**

OVERALL CONCLUSION **Fail**

Exceed the AQL and Refer to Remark: 2, 3, 4

Important Remarks:

1) For item 153185, 28 out of 49 inspected samples were moist in the Kettle, details as below:

2) For item 153185, discrepancies were found between digital photo provided by client and actual found:

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

	Photo provided by client	Actual found
	 logo on top of the plate	Logo was on one side of plate
3)	For item 153185, logo size was 44x13mm instead of 40x10.362mm required by client.	
4)	No CDF was provided by factory for checking during inspection.	

Reminding:

1)	NIL

Special Check Points For Client

1)	For all inspected products did not found any product leakage.	Conform
2)	For all inspected products that the controller were working well.	Conform
3)	For all inspected products did not find any smoke when boiling water.	Conform

1) QUANTITY CHECK : Pass

Order No.	Item/SKU/ Style No.	Order Qty	Shipment Qty		Packed in carton		Finished not packed		Sample Size		
									Packed		Unpacked
		(Units)	(Units)	(Carton)	Qty	%	Qty	%	(Units)	(Carton)	(Units)
	153185	2152	2152	1076	2152	100	0	0	49	27	0
	153186	6720	6720	560	6720	100	0	0	151	14	0
Total:		8872	8872	1636	8872	100	0	0	200	41	0

2) WORKMANSHIP : Fail, Exceed the AQL and Refer to remark: 1

Inspection Standard:	**ISO 2859**	**AQL**	**Accepted**	**Rejected**	**Total Found**	**Sample size**
Sampling Plan	: Single normal	**Critical** : **Not allowed**	**0**	**1**	**0**	**200**
Sampling Level	: Level II	**Major** : **1.5**	**7**	**8**	**0**	**200**
Sample Size	: 200 Pieces	**Minor** : **4.0**	**14**	**15**	**4**	**200**

No.	**Defects Description:**	**CRI**	**MAJ**	**MIN**
Item No.: 153185	**Sample Size: 49 Samples**			
1.	Dirty mark on surface	-	-	1
Item No.: 153186	**Sample Size: 151 Samples**			
2.	Scratch mark on surface	-	-	2
3.	Extra painting on water level	-	-	1

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

Sample

Total Found:	0	0	4

Representative Defects Photos:

dirty mark on surface(mi)

slightly scratch mark on surface 1(mi)



extra painting on water level(mi)

Note: Please refer to “Photo Attachment” For All defects photos.

3) PRODUCT DESCRIPTION/STYLE/COLOR :	Fail, Refer to remark: 2, 3, 4
Check points	**Result**
1. Check against PO	**Pass**
2. Check against product Spec	**Fail, Refer to remark: 3**
3. Check against samples/color swatch	**N/A**
4. Check against Photo(s)	**Fail, Refer to remark: 2**
5. Check against Instruction Manual	**Pass**
6. Check against component check	**Pending, Refer to remark: 4**

Table-3.1: Critical component compare to certificate:

Component description	Actual marking on component	Does the Marking comply with certificate?
Item No.: 153185		
- Plug	Wj-02 16A250V~	N/A
- Power cord	HOSVV-F 360.75mm2+ 300/500V	N/A
- Kettle control	No marking	N/A
- Cordless Kettle connector	G90-1 10A 250V	N/A
- Heating element	1500W 220V	N/A
- Thermostat *2	KSD 201 EC 125	N/A
Item No.: 153186		
- Plug	Wj-02 16A 250V~	N/A
- Power cord	HOSVV-F 360.75mm2+ 300/500V	N/A
- Kettle control	No marking	N/A
- Cordless Kettle connector	G90-T 10A 250V	N/A
- Heating element	1800W/220V	N/A
- Thermostat *2	KSD 201 EC 125	N/A

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer’s right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

“©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent”

Table-3.2: Product dimension / weight measurement:

Item	Sample size	Check points	Spec	Actual
153185	2pcs	Capacity	1.5L	1.6L, 1.7 L
		Body size	-	Tea set:185x130x140 cm Plate:41.7x20.5x3 cm Kettle:212x160x220 cm
		The length of power cord	-	99cm
		Rating label size	40x22mm	40x22mm
		Logo size on tea set	35x9.066mm	35x9mm
		Logo size on warm plate	45x11.565mm	45x12mm
		Logo size on Kettle	45x11.656mm	45x12mm
		Unit weight	-	Tea set: 350, 354, 353 Plate:672, 678, 672 Kettle:690, 682, 680 Power cord:136, 136, 135
153186	2pcs	Body size	-	220xx168x218mm
		The length of power cord	-	70cm
		Rating label size	40x22mm	40x22mm
		Logo size	40x10.362mm	**44x13mm**
		Unit weight	-	914, 910, 918

Photos of Product:

Note: Only item: 153185 was listed above for your reference, please refer to “PHOTO ATTACHMENT” for other items.

4) Labeling, Printing, Marking & Barcode :	Pass
Check points	**Result**
1. Barcode verification	**Pass**
2. Warning words / Label	**Pass**
3. Logo / Brand	**Pass**
4. Certificate mark / Other Symbol	**Pass**

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer’s right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

“©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent”

5.	**Artwork (Label/User manual/Warranty card/hang tag)**	**Pass**

Table-4.1: Logo/Warning/Symbol/Artwork:

Location	Name	Findings/Comments
Master carton	Logo, Barcode	Same as client's requirement
Gift box	Logo, GOST, GS, CE, Barcode,	Same as requirement
Product	Logo, rating label, GS, CE, GOST	Same as client's requirement
POLY BAG	Warning words, recycle mark, green dot	Same as general requirement

Photos of Logo, Labeling, Printing, Marking & Barcode:



N/A N/A

Note: Only item: 153185 was listed above for your reference, please refer to "PHOTO ATTACHMENT" for other items.

5) PACKAGING AND ASSORTMENT :	**Pass**
Check points	**Result**
1. Packaging checking	**Pass**
2. Carton quantity and assortment checking	**Pass**
3. Packing dimension and weight measurement	**Pass**

Table-5.1: Packaging checking

Item	Individual packing	Unit package	Inner carton	Outer carton
153185	tea set, plate, power cord, kettle	Styrofoam, poly bag	Color box	Double wall, sealed with white gummed tape, not fastened metal staples, strapped yellow nylon band.
Note: Only item: 153185 was listed above for your reference, please refer to "PHOTO ATTACHMENT" for other items.				

Table-5.2: Carton quantity and assortment checking

Item	Sample size	Quantity / inner carton	Quantity / outer cartoon

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

153185	3ctns	-	2pcs
153186	3ctns	-	12pcs

Table-5.3: Dimension / weight of individual package:

Item	Sample size	Specification	Actual
153185	2pcs	45.5x22.6x26.7cm/-	45.5x23x26.5cm/2.42kg for both
153186	2pcs	21.5x16.5x24.0cm/-	21.7x16.6x24.0cm/14.46kg for both

Table-5.4: Dimension / weight of master carton:

Item	Sample size	Specification	Actual
153185	1ctn	24x24x56cm/Nil	25x24.5x57cm/5.678 kg
153186	1ctn	51.5x45x50/Nil	53x45.5x52cm/14.458kg

Photos of Packaging:

Note: Only item: 153185 was listed above for your reference, please refer to “PHOTO ATTACHMENT” for other items.

6) SHIPPING MARK : Pass

Check points	Result
1. Product description (Name/Item/Reference No. etc)	Pass
2. Batch Number (PO No./Date code etc)	Pass
3. Shipping mark layout	Pass

Photos of Shipping mark:

Main mark (2 Sides) Side mark (2 Sides) Other mark (Sides)





N/A

Note: Only item: 153185 was listed above for your reference, please refer to “PHOTO ATTACHMENT” for other items.

7) ON-SITE TEST & DATA MEASUREMENT : Pass

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer’s right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

“©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent”

Check points	Sample Size	Result
1. Hi voltage check(AT 1500 V. for 1 sec)	200pcs	Pass
2. Earth Resistance Check (25A,≤0.1Ω)	200pcs	Pass
3. Base function check	200pcs	Pass
4. Power Consumption at 230 V 50 Hz	200samples	Pass
5. Internal Check for Workmanship	2pcs/item	Pass
6. Smell Check	2pcs/item	Pass
7. Water leakage check	2pcs/item	Pass
8. Rub and Tape Test on Logo and Printing	2pcs/item	Pass
9. Thermostat cut off check	2pcs/item	Pass
10. Strain Relief on Power Cord	2pcs/item	Pass
11. Stability Check at 10 Degree	2pcs/item	Pass
12. Power on Check for 4 Hours	2pcs/item	Pass
13. Real function check	2pcs/item	Pass

Table-7.1: Power consumption measurement: (W)

Item	Sample size	Setting / Specification	Actual
153185	49pcs	230V 50 Hz / 1500W	1396~1459W
153186	151pcs	230V 50 Hz / 1800W	1705~1772W

Table-7.2: Brewing temperature and time check (at max ;SPEC 98ºC, start temperature 9 ºC)

Item	Sample size	TIME	Actual
153185	2pcs	7'45";7'37"	98; 99 **ºC**
153186	2pcs	6'54";6'51"	99;99 **ºC**

Photos of On-site test:

Note: Only item: 153185 was listed above for your reference, please refer to "PHOTO ATTACHMENT" for other items.

NOTE

1) No carton No. was available in this inspection.
2) Manufacturer refused us to draw one production sample to ACCU office for reference.

ATTACHMENTS (List all documents attached to this report)

1) NIL

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

PHOTO ATTACHMENT

1 153185

P1) warehouse

P2) export carton

P3) gross weight of carton 1

P4) gross weight of carton 2

P5) gross weight of gift box 1

P6) gross weight of gift box 2

P7) empty weight of carton 1

P8) empty weight of gift box 2

P9) weight of Kettle 1

P10) weight of Kettle 2

P11) weight of tea set 1

P12) weight of plate 1

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P13) weight of plate 2

P14) weight of power cord 1

P15) weight of power cord 2

P16) dimension of carton 1

P17) dimension of carton 2

P18) dimension of carton 3

P19) dimension of gift box 1

P20) dimension of gift box 2



P21) dimension of gift box 3

P22) main mark 1

P23) main mark 2



P24) barcode

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P25) side mark

P26) barcodee

P27) export carton



P28) corrugate of carton

P29) gift box 1

P30) gift box 2

P31) gift box 4

P32) gift box 5

P33) gift box 6

P34) gift box 7

P35) gift box 8

P36) gift box 10

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P37) gift box 9



P38) gift box 11

P39) gift box 12

P40) gift box 13

P41) gift box 14



P42) gift box 3

P43) gift box packing 1

P44) gift box packing 2

P45) gift box packing 3

P46) gift box packing 4

P47) gift box packing 5

P48) gift box packing 6

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P49) gift box packing 7

P50) gift box packing 8

P51) gift box packing 9



P52) hand books

P53) instruction manual 1



P54) instruction manual 2

P55) instruction manual 3



P56) instruction manual 4



P57) instruction manual 5



P58) instruction manual 6



P59) warranty card1



P60) warranty card2

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"



P61) warranty card3



P62) warranty card4



P63) warranty card5



P64) warranty card6

P65) unit

P66) Kettle packing

WARNING
To avoid danger of suffocation keep this plastic bag away from babies and children. Do not use in cribs, beds, carriages or playpens. The thin film may cling to nose and mouth and prevent breathing. This bag is not a toy.
02

P67) printing on poly bag

P68) Kettle 1

P69) Kettle 2

P70) print

P71) power cord

P72) power cord 1

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P73) power cord 2

P74) power cord 3

P75) power cord 4

P76) power cord 5

P77) power cord 6

P78) power cord 7

P79) plate packing

P80) printing

P81) plate 1

P82) plate 2

P83) plate 3

P84) plate 4

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P85) plate 5

P86) plate 6

P87) plate 7

P88) plate 8

P89) plate 9



P90) internal check 1

P91) internal check 2

P92) internal check 3

P93) internal check 4

P94) internal check 5

P95) internal check 6

P96) internal check 7

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"



P97) internal check 8

P98) internal check 9

P99) remark- water in Kettle 2

P100) remark- water in Kettle 1

P101) defect-dirty mark on surface(mi)

P102) Kettle 3

P103) Kettle 4

P104) Kettle 5

P105) Kettle 6



P106) Kettle 7

P107) Kettle 8

P108) Kettle 9

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P109) Kettle 10

P110) empty weight of carton 2

P111) Kettle 11

P112) Kettle 12

P113) Kettle 13

P114) Kettle 14

DO NOT IMMERSE IN WATER
NICHT IN WASSER EINTAUCHEN
NE PLONGER L'APPAREIL DANS L'EAU
NIET ONDER DOMPELEN IN WATER
NO SUMERGIR ENAGUA

P115) Kettle 15

P116) tea set packing

P117) printing

P118) tea set 1

P119) tea set 2

P120) tea set 3

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

		
P121) empty weight of gift box 1	P122) tea set 4	P123) tea set 5
P124) tea set 6	P125) tea set 7	P126) tea set 8
		
P127) tea set 9	P128) tea set 10	P129) tea set 11
		N/A
P130) tea set 12	P131) power cord packing	N/A
2 153186		

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P132) export carton

P133) gross weight of carton 1

P134) gross weight of carton 2

P135) weight of empty carton 1

P136) weight of empty carton 2

P137) unit weight 1

P138) unit weight 2

P139) dimension of carton 1

P140) dimension of carton 2

P141) dimension of carton 3

P142) dimension of gift box 1



P143) dimension of gift box 2

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P144) dimension of gift box 3

P145) gross weight of gift box 1

P146) gross weight of gift box 2

P147) empty weight of gift box 1

P148) empty weight of gift box 2



P149) main mark



P150) barcode

P151) side mark



P152) barcode

P153) carton packing

P154) gift box 1



P155) gift box 2

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"



P156) gift box 3

P157) gift box 4

P158) gift box 5

P159) gift box 6

P160) gift box 7

P161) gift box 8

P162) gift box 9

P163) gift box 10

P164) gift box 11

P165) gift box packing 1

P166) gift box packing 2

P167) hand books

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"



P168) warranty card 1



P169) warranty card 2

P170) instruction manual 1



P171) instuuction manual 2

P172) Kettle packing

WARNING
To avoid danger of suffocation keep this plastic bag away from babies and children Do not use in cribs, buds, carriages or playpens. The thin film may cling to nose and mouth and prevent breathing. This bag is not a toy.
02

P173) printing on poly bag

P174) Kettle 1

P175) Kettle 2

P176) Kettle 3

P177) Kettle 4

P178) Kettle 5

P179) Kettle 6

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P180) Kettle 7

P181) Kettle 8

P182) Kettle 9

P183) Kettle 10

P184) Kettle 11

P185) Kettle 12

P186) Kettle 13

DO NOT IMMERSE IN WATER
NICHT IN WASSER EINTAUCHEN
NE JAMAIS PLONGER L'APPAREIL DANS L'EAU
NIET ONDER DOMPELEN IN WATER
NO SUMERGIR EN AGUA

P187) Kettle 14

P188) base packing

WARNING
To avoid danger of suffocation keep this plastic bag away from babies and children.Do not use in cribs, beds, carriages or playpens. The thin film may cling to nose and mouth and prevent breathing. This bag is not a toy.
02

P189) printing on poly bag

P190) base 1

P191) base 2

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

P192) base 3

P193) base 5

P194) base 4

P195) base 6

P196) plug

P197) marking on cord

P198) internal check 1

P199) internal check 2



P200) internal check 3

P201) internal check 4

P202) internal check 5

P203) internal check 6

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"

		
P204) logo size 1	***P205) logo size 2***	***P206) defect-slightly scratch mark on surface 1(mi)***
		***N/A***
P207) defect-slightly scratch mark on surface 2(mi)	***P208) defect-extra painting on water level(mi)***	***N/A***

------END OF THE REPORT------

Sample

This report reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

"©2003-2010 AccuInspection All rights reserved. Do not disclose outside your organization without AccuInspection prior written consent"